

The cost estimate of Mechnykova street,106, Irpin, Kyiv region

| | Cost of materials | | Cost of work | | Total | |
|--|-------------------|------------------|-------------------|--------------------|--------------------|--------------------|
| | UA | EURO | UA | EURO | UA | EURO |
| Repair of ceilings, walls, floors | 1598208,00 | 52297,38 | 2559228 | 83744,37 | 4157436,00 | 136041,75 |
| Repair of elevator equipment | 613442,40 | 20073,38 | 242240,4 | 7926,71 | 855682,80 | 28000,09 |
| Repair and replacement of Windows / doors | 4092982,80 | 133932,68 | 337154,4 | 11032,53 | 4430137,20 | 144965,22 |
| Power supply system | 146912,40 | 4807,34 | 266628 | 8724,73 | 413540,40 | 13532,08 |
| Roof, façade | 1651180,80 | 54030,79 | 1895022 | 62009,88 | 3546202,80 | 116040,67 |
| Water supply system | 16454,40 | 538,43 | 940671,6 | 30781,13 | 957126,00 | 31319,56 |
| Additional costs | | | 4775918,4 | 156280,0524 | 4775918,40 | 156280,05 |
| Author's and technical supervision | - | | 1191881 | 39001,34162 | 1191881,00 | 39001,34 |
| Total estimates | 8119180,80 | 265680,00 | 12208743,8 | 399500,7788 | 20327924,60 | 665180,7788 |